

VIN: WVWPR7AU3KW909283 2019 Volkswagen e-Golf SEL Premium Odometer: 53,000 miles

2184 E Colorado Blvd, Pasadena, CA 91107 cars@surplusev.com

VEHICLE INSPECTION REPORT

VEHICLE HISTORY

#	Checklist Item	Status	Notes
1	Verified Presence and Accuracy of VIN Plates	~	
2	No Reported Frame Damage or Airbag Deployment	~	
3	No Reported Odometer Rollback	~	
4	No Reported Salvaged, Junk, Flood or Lemon Title Branding	~	
5	Checked CARFAX for Reported Accidents		Minor Accident
6	Check Recall Database for Open Safety-Related Recal	lls.	

LIGHTS

#	Checklist Item	Status	Notes
1	Headlight Operation	~	
2	High Beam Operation	~	
3	Front and Rear Turn Signal Operation	~	
4	Tail Light Operation	~	
5	Brake Lights Operation	~	
6	Hazard Lights Operation	~	
7	License Plate Light Operation	~	

TIRES

#	Checklist Item	Status	Notes
1	Minimum Tread Depth of 4/32"	~	

Tire Pressure Set to Manufacturer Recommended PSI
Tire Condition

EXTERIOR

#	Checklist Item	Status	Notes
1	Key Fob Operation	~	
2	Wiper Fluid Check	~	
3	Front Bumper Condition	A	Low visibility scrape
4	Driver Side Fender Condition	~	•
5	Passenger Side Fender Condition	A	Small dent
6	Hood	A	Stone chips and scratches
7	Driver Side Door	A	Door ding and scratch
8	Passenger Side Door	~	
9	Driver Side Rear Door	~	
10	Passenger Side Rear Door	~	
11	Driver Side Quarter Panel	A	Door ding
12	Passenger Side Quarter Panel	A	Light scratches
13	Trunk/Liftgate Condition	~	
14	Rear Bumper Condition	A	Moderate scratches on top
15	Roof Condition	~	coratorios en top
16	Driver Side Front Wheel	~	
17	Driver Side Rear Wheel	~	
18	Passenger Side Front Wheel	~	
19	Passenger Side Rear Wheel	~	
20	Windshield Condition	~	

INTERIOR

#	Checklist Item	Status	Notes
1	Front Passengers Seat Belt Operation	~	
2	Rear Passengers Seat Belt Operation	~	
3	Steering Wheel Tilt/Telescoping	~	
4	Rear Camera Operation	~	
5	Driver Seat Operation	~	
6	Passenger Seat Operation	~	
7	Glove Box Operation	~	
8	Window Operation	~	
9	Trunk/Liftgate Operation	~	
10	12V/Power Outlet Operation	~	
11	A/C Function	~	
12	Heater Function	~	
13	Sunvisor Operation	~	
14	Rearview Mirror Operation	~	
15	Driver Side Mirror Operation	~	
16	Passenger Side Mirror Operation	~	
17	Headliner Condition	~	
18	Steering Wheel Condition	~	
19	Windshield Wiper Function	~	
20	Infotainment and Stereo Operation	~	

ROAD TEST

#	Checklist Item	Status	Notes
1	City Road Test	~	
2	Highway Road Test	~	

3	Cruise Control	✓
4	Regenerative Braking Operation	✓
5	Hard Braking Test	✓
6	Parking Brake Operation	~

CHARGING

#	Checklist Item	Status	Notes
1	Charge Port Door Operation	~	
2	120V Charging (Level 1)	~	
3	240V Charging (Level 2)	~	

DETAILING

#	Checklist Item	Status	Notes
1	Exterior Car Wash and Decontamination	~	
2	Exterior Glass Cleaned	~	
3	Interior Glass Cleaned	~	
4	Seating Surfaces Cleaned	~	
5	Dashboard, Steering Wheel and Interior Door Panels Cleaned	~	
6	Interior Vacuumed	~	
7	Odor Check	~	
8	Tire Dressing Applied	~	