

2184 E Colorado Blvd, Pasadena, CA 91107 cars@surplusev.com

VIN: 1G1FZ6S05P4150617 2023 Chevrolet Bolt EUV Premier Odometer: 25,900 miles

VEHICLE INSPECTION REPORT

VEHICLE HISTORY

#	Checklist Item	Status	Notes
1	Verified Presence and Accuracy of VIN Plates	~	
2	No Reported Frame Damage or Airbag Deployment	~	
3	No Reported Odometer Rollback	~	
4	No Reported Salvaged, Junk, Flood or Lemon Title Branding	~	
5	Checked CARFAX for Reported Accidents	~	
6	Check Recall Database for Open Safety-Related Recal	ls. ,	

LIGHTS

#	Checklist Item	Status	Notes
1	Headlight Operation	~	
2	High Beam Operation	~	
3	Front and Rear Turn Signal Operation	✓	
4	Tail Light Operation	✓	
5	Brake Lights Operation	~	
6	Hazard Lights Operation	✓	
7	License Plate Light Operation	~	

TIRES

#	Checklist Item	Status	Notes
1	Minimum Tread Depth of 4/32"	~	

- 3 Tire Condition

EXTERIOR

#	Checklist Item	Status	Notes
1	Key Fob Operation	~	
2	Wiper Fluid Check	~	
3	Front Bumper Condition	~	
4	Driver Side Fender Condition	~	
5	Passenger Side Fender Condition	~	
6	Hood	~	
7	Driver Side Door	~	
8	Passenger Side Door	~	
9	Driver Side Rear Door	~	
10	Passenger Side Rear Door	~	
11	Driver Side Quarter Panel	~	
12	Passenger Side Quarter Panel	~	
13	Trunk/Liftgate Condition	~	
14	Rear Bumper Condition	~	
15	Roof Condition	~	
16	Driver Side Front Wheel	~	
17	Driver Side Rear Wheel	~	
18	Passenger Side Front Wheel	~	
19	Passenger Side Rear Wheel	~	

INTERIOR

#	Checklist Item	Status	Notes
1	Driver Seatbelt Operation	~	
2	Passenger Seatbelt Operation	~	
3	Rear Passengers Seatbelt Operation	~	
4	Steering Wheel Tilt/Telescoping	~	
5	Rear Camera Operation	~	
6	Driver Seat Operation	~	
7	Passenger Seat Operation	~	
8	Glove Box Operation	~	
9	Window Operation	~	
10	Trunk/Liftgate Operation	~	
11	12V/Power Outlet Operation	~	
12	A/C Function	~	
13	Heater Function	~	
14	Sunvisor Operation	~	
15	Rearview Mirror Operation	~	
16	Driver Side Mirror Operation	~	
17	Passenger Side Mirror Operation	~	
18	Headliner Condition	~	
19	Steering Wheel Condition	~	
20	Windshield Wiper Function	~	
21	Infotainment and Stereo Operation	~	

ROAD TEST

#	Checklist Item	Status	Notes
1	City Road Test	~	

2	Highway Road Test	~
3	Cruise Control	~
4	Regenerative Braking Operation	~
5	Hard Braking Test	✓
6	Parking Brake Operation	✓

CHARGING

#	Checklist Item	Status	Notes
1	Charge Port Door Operation	~	
2	120V Charging (Level 1)	✓	
3	240V Charging (Level 2)	~	

DETAILING

#	Checklist Item	Status	Notes
1	Exterior Car Wash and Decontamination	~	
2	Exterior Glass Cleaned	~	
3	Interior Glass Cleaned	~	
4	Seating Surfaces Cleaned	~	
5	Dashboard, Steering Wheel and Interior Door Panels Cleaned	~	
6	Interior Vacuumed	~	
7	Odor Check	~	
8	Tire Dressing Applied	~	