



VIN: KNDC5DLE0P5117426  
2023 Kia EV6 GT  
Odometer: 450 miles

2184 E Colorado Blvd, Pasadena, CA 91107  
cars@surplusev.com

## VEHICLE INSPECTION REPORT

### VEHICLE HISTORY

#	Checklist Item	Status	Notes
1	Verified Presence and Accuracy of VIN Plates	✓	
2	No Reported Frame Damage or Airbag Deployment	✓	
3	No Reported Odometer Rollback	✓	
4	No Reported Salvaged, Junk, Flood or Lemon Title Branding	✓	
5	Checked CARFAX for Reported Accidents	✓	
6	Check Recall Database for Open Safety-Related Recalls	✓	

### LIGHTS

#	Checklist Item	Status	Notes
1	Headlight Operation	✓	
2	High Beam Operation	✓	
3	Front and Rear Turn Signal Operation	✓	
4	Tail Light Operation	✓	
5	Brake Lights Operation	✓	
6	Hazard Lights Operation	✓	
7	License Plate Light Operation	✓	

### TIRES

#	Checklist Item	Status	Notes
1	Minimum Tread Depth of 4/32"	✓	

2	Tire Pressure Set to Manufacturer Recommended PSI	✓
3	Tire Condition	✓

## EXTERIOR

#	Checklist Item	Status	Notes
1	Key Fob Operation	✓	
2	Wiper Fluid Check	✓	
3	Front Bumper Condition	⚠	Chip on bumper
4	Driver Side Fender Condition	✓	
5	Passenger Side Fender Condition	✓	
6	Hood	✓	
7	Driver Side Door	✓	
8	Passenger Side Door	⚠	Door ding
9	Driver Side Rear Door	⚠	Scratches on trim above driver side door
10	Passenger Side Rear Door	⚠	Door ding
11	Driver Side Quarter Panel	✓	
12	Passenger Side Quarter Panel	✓	
13	Trunk/Liftgate Condition	✓	
14	Rear Bumper Condition	✓	
15	Roof Condition	⚠	Light scratches on roof
16	Driver Side Front Wheel	✓	
17	Driver Side Rear Wheel	✓	
18	Passenger Side Front Wheel	✓	
19	Passenger Side Rear Wheel	✓	
20	Windshield Condition	⚠	Damage in corner of windshield outside of driver sightline

## INTERIOR

#	Checklist Item	Status	Notes
1	Front Passengers Seat Belt Operation	✓	
2	Rear Passengers Seat Belt Operation	✓	
3	Steering Wheel Tilt/Telescoping	✓	
4	Rear Camera Operation	✓	
5	Driver Seat Operation	✓	
6	Passenger Seat Operation	✓	
7	Glove Box Operation	✓	
8	Window Operation	✓	
9	Trunk/Liftgate Operation	✓	
10	12V/Power Outlet Operation	✓	
11	A/C Function	✓	
12	Heater Function	✓	
13	Sunvisor Operation	✓	
14	Rearview Mirror Operation	✓	
15	Driver Side Mirror Operation	⚠	Light scuff on driver side mirror cap
16	Passenger Side Mirror Operation	✓	
17	Headliner Condition	✓	
18	Steering Wheel Condition	✓	
19	Windshield Wiper Function	✓	
20	Infotainment and Stereo Operation	✓	

## ROAD TEST

#	Checklist Item	Status	Notes
1	City Road Test	✓	
2	Highway Road Test	✓	

3	Cruise Control	✓
4	Regenerative Braking Operation	✓
5	Hard Braking Test	✓
6	Parking Brake Operation	✓

## CHARGING

#	Checklist Item	Status	Notes
1	Charge Port Door Operation	✓	
2	120V Charging (Level 1)	✓	
3	240V Charging (Level 2)	✓	

## DETAILING

#	Checklist Item	Status	Notes
1	Exterior Car Wash and Decontamination	✓	
2	Exterior Glass Cleaned	✓	
3	Interior Glass Cleaned	✓	
4	Seating Surfaces Cleaned	✓	
5	Dashboard, Steering Wheel and Interior Door Panels Cleaned	✓	
6	Interior Vacuumed	✓	
7	Odor Check	✓	
8	Tire Dressing Applied	✓	