

2184 E Colorado Blvd, Pasadena, CA 91107 cars@surplusev.com

# **VEHICLE INSPECTION REPORT**

## **VEHICLE HISTORY**

#	Checklist Item	Status	Notes
1	Verified Presence and Accuracy of VIN Plates	<b>~</b>	
2	No Reported Frame Damage or Airbag Deployment	<b>~</b>	
3	No Reported Odometer Rollback	~	
4	No Reported Salvaged, Junk, Flood or Lemon Title Branding	<b>~</b>	
5	Checked CARFAX for Reported Accidents	<b>~</b>	
6	Check Recall Database for Open Safety-Related Recalls	<u> </u>	

#### **LIGHTS**

#	Checklist Item	Status	Notes
1	Headlight Operation	<b>~</b>	
2	High Beam Operation	<b>~</b>	
3	Front and Rear Turn Signal Operation	<b>~</b>	
4	Tail Light Operation	<b>~</b>	
5	Brake Lights Operation	<b>~</b>	
6	Hazard Lights Operation	<b>~</b>	
7	License Plate Light Operation	~	

#### **TIRES**

#	Checklist Item	Status	Notes
1	Minimum Tread Depth of 4/32"	<b>~</b>	

2	Tire Pressure Set to Manufacturer Recommended PSI	<b>✓</b>
3	Tire Condition	<b>✓</b>

## **EXTERIOR**

#	Checklist Item	Status	Notes
1	Key Fob Operation	<b>~</b>	
2	Wiper Fluid Check	<b>~</b>	
3	Front Bumper Condition	<b>~</b>	
4	Driver Side Fender Condition	<b>~</b>	
5	Passenger Side Fender Condition	<b>~</b>	
6	Hood	<b>~</b>	
7	Driver Side Door	<b>~</b>	
8	Passenger Side Door	<b>~</b>	
9	Driver Side Rear Door	<b>~</b>	
10	Passenger Side Rear Door	<b>~</b>	
11	Driver Side Quarter Panel	<b>~</b>	
12	Passenger Side Quarter Panel	<b>~</b>	
13	Trunk/Liftgate Condition	<b>~</b>	
14	Rear Bumper Condition	<b>~</b>	
15	Roof Condition	<b>~</b>	
16	Driver Side Front Wheel	<b>~</b>	
17	Driver Side Rear Wheel	<b>~</b>	
18	Passenger Side Front Wheel	<b>~</b>	
19	Passenger Side Rear Wheel	<b>~</b>	
20	Windshield Condition	<b>~</b>	

## **INTERIOR**

# Checklist Item Status Notes

1	Front Passengers Seat Belt Operation	<b>✓</b>
2	Rear Passengers Seat Belt Operation	<b>✓</b>
3	Steering Wheel Tilt/Telescoping	<b>~</b>
4	Rear Camera Operation	~
5	Driver Seat Operation	~
6	Passenger Seat Operation	~
7	Glove Box Operation	~
8	Window Operation	<b>✓</b>
9	Trunk/Liftgate Operation	<b>✓</b>
10	12V/Power Outlet Operation	<b>✓</b>
11	A/C Function	~
12	Heater Function	~
13	Sunvisor Operation	<b>~</b>
14	Rearview Mirror Operation	<b>✓</b>
15	Driver Side Mirror Operation	<b>~</b>
16	Passenger Side Mirror Operation	<b>✓</b>
17	Headliner Condition	~
18	Steering Wheel Condition	<b>✓</b>
19	Windshield Wiper Function	<b>~</b>
20	Infotainment and Stereo Operation	<b>✓</b>

# **ROAD TEST**

#	Checklist Item	Status	Notes
1	City Road Test	<b>~</b>	
2	Highway Road Test	<b>~</b>	
3	Cruise Control	<b>~</b>	
4	Regenerative Braking Operation	<b>~</b>	

5	Hard Braking Test	<b>~</b>
6	Parking Brake Operation	<b>✓</b>

# **CHARGING**

#	Checklist Item	Status	Notes
1	Charge Port Door Operation	~	
2	120V Charging (Level 1)	<b>~</b>	
3	240V Charging (Level 2)	~	

# **DETAILING**

#	Checklist Item	Status	Notes
1	Exterior Car Wash and Decontamination	<b>~</b>	
2	Exterior Glass Cleaned	<b>~</b>	
3	Interior Glass Cleaned	<b>~</b>	
4	Seating Surfaces Cleaned	~	
5	Dashboard, Steering Wheel and Interior Door Panels Cleaned	~	
6	Interior Vacuumed	<b>~</b>	
7	Odor Check	<b>~</b>	
8	Tire Dressing Applied	<b>~</b>	