



VIN: 3GPKHXRJ8RS500269
2024 Honda Prologue Touring
Odometer: 5,300 miles

2184 E Colorado Blvd, Pasadena, CA 91107
cars@surplusev.com

VEHICLE INSPECTION REPORT

VEHICLE HISTORY

| # | Checklist Item | Status | Notes |
|---|---|--------|-------|
| 1 | Verified Presence and Accuracy of VIN Plates | ✓ | |
| 2 | No Reported Frame Damage or Airbag Deployment | ✓ | |
| 3 | No Reported Odometer Rollback | ✓ | |
| 4 | No Reported Salvaged, Junk, Flood or Lemon Title Branding | ✓ | |
| 5 | Checked CARFAX for Reported Accidents | ✓ | |
| 6 | Check Recall Database for Open Safety-Related Recalls | ✓ | |

LIGHTS

| # | Checklist Item | Status | Notes |
|---|--------------------------------------|--------|-------|
| 1 | Headlight Operation | ✓ | |
| 2 | High Beam Operation | ✓ | |
| 3 | Front and Rear Turn Signal Operation | ✓ | |
| 4 | Tail Light Operation | ✓ | |
| 5 | Brake Lights Operation | ✓ | |
| 6 | Hazard Lights Operation | ✓ | |
| 7 | License Plate Light Operation | ✓ | |

TIRES

| # | Checklist Item | Status | Notes |
|---|------------------------------|--------|-------|
| 1 | Minimum Tread Depth of 4/32" | ✓ | |

| | | |
|---|---|---|
| 2 | Tire Pressure Set to Manufacturer Recommended PSI | ✓ |
| 3 | Tire Condition | ✓ |

EXTERIOR

| # | Checklist Item | Status | Notes |
|----|---------------------------------|--------|-------------------|
| 1 | Key Fob Operation | ✓ | |
| 2 | Wiper Fluid Check | ✓ | |
| 3 | Front Bumper Condition | ✓ | |
| 4 | Driver Side Fender Condition | ✓ | |
| 5 | Passenger Side Fender Condition | ⚠ | Small stone chips |
| 6 | Hood | ✓ | |
| 7 | Driver Side Door | ✓ | |
| 8 | Passenger Side Door | ✓ | |
| 9 | Driver Side Rear Door | ✓ | |
| 10 | Passenger Side Rear Door | ✓ | |
| 11 | Driver Side Quarter Panel | ✓ | |
| 12 | Passenger Side Quarter Panel | ✓ | |
| 13 | Trunk/Liftgate Condition | ✓ | |
| 14 | Rear Bumper Condition | ✓ | |
| 15 | Roof Condition | ✓ | |
| 16 | Driver Side Front Wheel | ✓ | |
| 17 | Driver Side Rear Wheel | ✓ | |
| 18 | Passenger Side Front Wheel | ✓ | |
| 19 | Passenger Side Rear Wheel | ✓ | |

INTERIOR

| # | Checklist Item | Status | Notes |
|----|------------------------------------|--------|-------|
| 1 | Driver Seatbelt Operation | ✓ | |
| 2 | Passenger Seatbelt Operation | ✓ | |
| 3 | Rear Passengers Seatbelt Operation | ✓ | |
| 4 | Steering Wheel Tilt/Telescoping | ✓ | |
| 5 | Rear Camera Operation | ✓ | |
| 6 | Driver Seat Operation | ✓ | |
| 7 | Passenger Seat Operation | ✓ | |
| 8 | Glove Box Operation | ✓ | |
| 9 | Window Operation | ✓ | |
| 10 | Trunk/Liftgate Operation | ✓ | |
| 11 | 12V/Power Outlet Operation | ✓ | |
| 12 | A/C Function | ✓ | |
| 13 | Heater Function | ✓ | |
| 14 | Sunvisor Operation | ✓ | |
| 15 | Rearview Mirror Operation | ✓ | |
| 16 | Driver Side Mirror Operation | ✓ | |
| 17 | Passenger Side Mirror Operation | ✓ | |
| 18 | Headliner Condition | ✓ | |
| 19 | Steering Wheel Condition | ✓ | |
| 20 | Windshield Wiper Function | ✓ | |
| 21 | Infotainment and Stereo Operation | ✓ | |

ROAD TEST

| # | Checklist Item | Status | Notes |
|---|----------------|--------|-------|
| 1 | City Road Test | ✓ | |

| | | |
|---|--------------------------------|---|
| 2 | Highway Road Test | ✓ |
| 3 | Cruise Control | ✓ |
| 4 | Regenerative Braking Operation | ✓ |
| 5 | Hard Braking Test | ✓ |
| 6 | Parking Brake Operation | ✓ |

CHARGING

| # | Checklist Item | Status | Notes |
|---|----------------------------|--------|-------|
| 1 | Charge Port Door Operation | ✓ | |
| 2 | 120V Charging (Level 1) | ✓ | |
| 3 | 240V Charging (Level 2) | ✓ | |

DETAILING

| # | Checklist Item | Status | Notes |
|---|--|--------|-------|
| 1 | Exterior Car Wash and Decontamination | ✓ | |
| 2 | Exterior Glass Cleaned | ✓ | |
| 3 | Interior Glass Cleaned | ✓ | |
| 4 | Seating Surfaces Cleaned | ✓ | |
| 5 | Dashboard, Steering Wheel and Interior Door Panels Cleaned | ✓ | |
| 6 | Interior Vacuumed | ✓ | |
| 7 | Odor Check | ✓ | |
| 8 | Tire Dressing Applied | ✓ | |
