2184 E Colorado Blvd, Pasadena, CA 91107 cars@surplusev.com

VEHICLE INSPECTION REPORT

VEHICLE HISTORY

#	Checklist Item	Status	Notes
1	Verified Presence and Accuracy of VIN Plates	~	
2	No Reported Frame Damage or Airbag Deployment	\checkmark	
3	No Reported Odometer Rollback	\checkmark	
4	No Reported Salvaged, Junk, Flood or Lemon Title Branding	\checkmark	
5	Checked CARFAX for Reported Accidents	\checkmark	
6	Check Recall Database for Open Safety-Related Reca	lls 🗸	

LIGHTS

#	Checklist Item	Status	Notes
1	Headlight Operation	\checkmark	
2	High Beam Operation	\checkmark	
3	Front and Rear Turn Signal Operation	\checkmark	
4	Tail Light Operation	\checkmark	
5	Brake Lights Operation	\checkmark	
6	Hazard Lights Operation	~	
7	License Plate Light Operation	\checkmark	

TIRES

#	Checklist Item	Status	Notes
1	Minimum Tread Depth of 4/32"	\checkmark	
2	Tire Pressure Set to Manufacturer Recommended PSI	\checkmark	

3	Tire Condition	l
-		

EXTERIOR

#	Checklist Item	Status	Notes
1	Key Fob Operation	~	
2	Wiper Fluid Check	~	
3	Front Bumper Condition	A	Lower bumper scrape
4	Driver Side Fender Condition	~	
5	Passenger Side Fender Condition	\checkmark	
6	Hood	\checkmark	
7	Driver Side Door	A	Marks on lower rocker panel
8	Passenger Side Door	~	·
9	Driver Side Rear Door	Not Applicable	
10	Passenger Side Rear Door	Not Applicable	
11	Driver Side Quarter Panel	\checkmark	
12	Passenger Side Quarter Panel	~	
13	Trunk/Liftgate Condition	\checkmark	
14	Rear Bumper Condition	A	Small mark on lower bumper
15	Roof Condition	A	Light scratches
16	Driver Side Front Wheel	~	
17	Driver Side Rear Wheel	~	
18	Passenger Side Front Wheel	A	Rim rash
19	Passenger Side Rear Wheel	A	Rim rash
20	Windshield Condition	~	

INTERIOR

#	Checklist Item	Status	Notes
1	Front Passengers Seat Belt Operation	~	
2	Rear Passengers Seat Belt Operation	~	
3	Steering Wheel Tilt/Telescoping	\checkmark	
4	Rear Camera Operation	\checkmark	
5	Driver Seat Operation	\checkmark	
6	Passenger Seat Operation	\checkmark	
7	Glove Box Operation	\checkmark	
8	Window Operation	\checkmark	
9	Trunk/Liftgate Operation	\checkmark	
10	12V/Power Outlet Operation	\checkmark	
11	A/C Function	\checkmark	
12	Heater Function	\checkmark	
13	Sunvisor Operation	\checkmark	
14	Rearview Mirror Operation	\checkmark	
15	Driver Side Mirror Operation	\checkmark	
16	Passenger Side Mirror Operation	\checkmark	
17	Headliner Condition	\checkmark	
18	Steering Wheel Condition	\checkmark	
19	Windshield Wiper Function	\checkmark	
20	Infotainment and Stereo Operation	\checkmark	

ROAD TEST

#	Checklist Item	Status	Notes
1	City Road Test	A	Small rattle in driver side door
2	Highway Road Test	\checkmark	

3	Cruise Control	\checkmark
4	Regenerative Braking Operation	\checkmark
5	Hard Braking Test	\checkmark
6	Parking Brake Operation	\checkmark

CHARGING

#	Checklist Item	Status	Notes
1	Charge Port Door Operation	\checkmark	
2	120V Charging (Level 1)	\checkmark	
3	240V Charging (Level 2)	Not Applicable	

DETAILING

#	Checklist Item	Status	Notes
1	Exterior Car Wash and Decontamination	\checkmark	
2	Exterior Glass Cleaned	~	
3	Interior Glass Cleaned	\checkmark	
4	Seating Surfaces Cleaned	\checkmark	
5	Dashboard, Steering Wheel and Interior Door Panels Cleaned	\checkmark	
6	Interior Vacuumed	\checkmark	
7	Odor Check	\checkmark	
8	Tire Dressing Applied	\checkmark	