

# SURPLUS EV

2184 E Colorado Blvd, Pasadena, CA 91107  
cars@surplusev.com

VIN: JN1DF0CD9PM706260  
2023 Nissan Ariya Platinum+  
Odometer: 7,900 miles

---

## VEHICLE INSPECTION REPORT

### VEHICLE HISTORY

#	Checklist Item	Status	Notes
1	Verified Presence and Accuracy of VIN Plates	✓	
2	No Reported Frame Damage or Airbag Deployment	✓	
3	No Reported Odometer Rollback	✓	
4	No Reported Salvaged, Junk, Flood or Lemon Title Branding	✓	
5	Checked CARFAX for Reported Accidents	✓	
6	Check Recall Database for Open Safety-Related Recalls	✓	

### LIGHTS

#	Checklist Item	Status	Notes
1	Headlight Operation	✓	
2	High Beam Operation	✓	
3	Front and Rear Turn Signal Operation	✓	
4	Tail Light Operation	✓	
5	Brake Lights Operation	✓	
6	Hazard Lights Operation	✓	
7	License Plate Light Operation	✓	

### TIRES

#	Checklist Item	Status	Notes
1	Minimum Tread Depth of 4/32"	✓	
2	Tire Pressure Set to Manufacturer Recommended PSI	✓	

3	Tire Condition	✓	
---	----------------	---	--

## EXTERIOR

#	Checklist Item	Status	Notes
1	Key Fob Operation	✓	
2	Wiper Fluid Check	✓	
3	Front Bumper Condition	✓	
4	Driver Side Fender Condition	✓	
5	Passenger Side Fender Condition	⚠	Visible scuffs
6	Hood	✓	
7	Driver Side Door	✓	
8	Passenger Side Door	✓	
9	Driver Side Rear Door	✓	
10	Passenger Side Rear Door	✓	
11	Driver Side Quarter Panel	✓	
12	Passenger Side Quarter Panel	✓	
13	Trunk/Liftgate Condition	⚠	Small paint chip
14	Rear Bumper Condition	✓	
15	Roof Condition	✓	
16	Driver Side Front Wheel	✓	
17	Driver Side Rear Wheel	✓	
18	Passenger Side Front Wheel	✓	
19	Passenger Side Rear Wheel	✓	

## INTERIOR

#	Checklist Item	Status	Notes
1	Driver Seatbelt Operation	✓	

2	Passenger Seatbelt Operation	✓	
3	Rear Passengers Seatbelt Operation	✓	
4	Steering Wheel Tilt/Telescoping	✓	
5	Rear Camera Operation	✓	
6	Driver Seat Operation	✓	
7	Passenger Seat Operation	✓	
8	Glove Box Operation	✓	
9	Window Operation	✓	
10	Trunk/Liftgate Operation	✓	
11	12V/Power Outlet Operation	✓	
12	A/C Function	✓	
13	Heater Function	✓	
14	Sunvisor Operation	✓	
15	Rearview Mirror Operation	✓	
16	Driver Side Mirror Operation	⚠	Minor scuff on mirror cap
17	Passenger Side Mirror Operation	✓	
18	Headliner Condition	✓	
19	Steering Wheel Condition	✓	
20	Windshield Wiper Function	✓	
21	Infotainment and Stereo Operation	✓	

## ROAD TEST

#	Checklist Item	Status	Notes
1	City Road Test	✓	
2	Highway Road Test	✓	
3	Cruise Control	✓	
4	Regenerative Braking Operation	✓	

5	Hard Braking Test	✓
6	Parking Brake Operation	✓

## CHARGING

#	Checklist Item	Status	Notes
1	Charge Port Door Operation	✓	
2	120V Charging (Level 1)	✓	
3	240V Charging (Level 2)	✓	

## DETAILING

#	Checklist Item	Status	Notes
1	Exterior Car Wash and Decontamination	✓	
2	Exterior Glass Cleaned	✓	
3	Interior Glass Cleaned	✓	
4	Seating Surfaces Cleaned	✓	
5	Dashboard, Steering Wheel and Interior Door Panels Cleaned	✓	
6	Interior Vacuumed	✓	
7	Odor Check	✓	
8	Tire Dressing Applied	✓	

---